

ORIGINAL



0000166774

COMMISSIONERS

SUSAN BITTER SMITH-CHAIRWOMAN  
BOB BURNS  
BOB STUMP  
DOUG LITTLE  
TOM FORESE

RECEIVED

2015 NOV 10 P 12: 26


AZ CORP COMMISSION  
DOCKET CONTROL

DOCKET NOS.: W-04254A-12-0204; W-04254A-12-0205; W-04254A-12-0206; W-04254A-12-0207; W-04254A-11-0323; W-04254A-08-0361; W-04254A-08-0362

Arizona Corporation Commission

DOCKETED

NOV 10 2015




DECISION NO. 74504

NOTICE OF FILING

MONTEZUMA RIMROCK WATER COMPANY LLC

COMPLIANCE REPORT

# *Montezuma Rimrock Water Company, LLC*



3031 E. Beaver Creek Rd., Rimrock, AZ 86335

[www.MontezumaWater.com](http://www.MontezumaWater.com)

Phone: 928-592-9211

November 5, 2015

Decision NO. 74504, docketed on May 30, 2014, requires Montezuma Rimrock Water Company LLC (MRWC) to submit a compliance report every six months from the effective date of this Decision for a period of two years.

In compliance with Decision NO. 74504:

MRWC has not engaged in any long term contracts and does not intend to without prior Arizona Corporation Commission approval.

MRWC has not received an AOC from ADEQ for the hydropneumatic tank. MRWC was not provided an adequate rate increase to allow funding to engage an engineer for the AOC of the hydropneumatic tank or funds for the installation of the hydropneumatic tank. It has not implemented any surcharges to its customers in association with the hydropneumatic tank and to date the hydropneumatic tank has not been installed. Due to the extensive delays and unavailable funding, the hydropneumatic tank will no longer be available to MRWC as of January 1, 2016.

MRWC has not executed the WIFA loan authorized by the ACC. WIFA has not allowed MRWC to move forward with the WIFA loan. MRWC has not implemented any surcharges to its customers in association with the WIFA storage tank loan.

Submitted by,

Patricia D. Olsen